

10 CFR 50.73(a)(2)(iv)(A)

January 21, 2003


U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

DOCKET 50-255
LICENSE DPR-20
PALISADES NUCLEAR PLANT
LICENSEE EVENT REPORT 02-002, AUTOMATIC REACTOR TRIP AND SAFETY
SYSTEM ACTUATION

Licensee Event Report (LER) 02-002 is attached. The LER describes an automatic reactor trip and subsequent actuation of the auxiliary feedwater system. This event is reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A).

SUMMARY OF COMMITMENTS

This letter contains no new commitments and no revisions to existing commitments.



Douglas E. Cooper
Site Vice-President, Palisades

CC Regional Administrator, USNRC, Region III
Project Manager, USNRC, NRR
NRC Resident Inspector, Palisades

Attachment

LICENSEE EVENT REPORT (LER)

(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

PALISADES NUCLEAR PLANT

2. DOCKET NUMBER

05000255

3. PAGE

1 OF 3

4. TITLE

AUTOMATIC REACTOR TRIP AND SAFETY SYSTEM ACTUATION

5. EVENT DATE

MO DAY YEAR
12 01 2002

6. LER NUMBER

YEAR SEQUENTIAL REV
2002 - 002 - 00

7. REPORT DATE

MO DAY YEAR
01 21 2003

8. OTHER FACILITIES INVOLVED

FACILITY NAME DOCKET NUMBER
FACILITY NAME DOCKET NUMBER9. OPERATING
MODE

1

10. POWER
LEVEL

100

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50.73(a)(2)(iv)(A) (Check all that apply)

| | | | |
|--------------------|--------------------|----------------------|---------------------------------|
| 20 2201(b) | 20 2203(a)(3)(ii) | 50 73(a)(2)(ii)(B) | 50 73(a)(2)(ix)(A) |
| 20 2201(d) | 20 2203(a)(4) | 50 73(a)(2)(iii) | 50 73(a)(2)(x) |
| 20 2203(a)(1) | 50.36(c)(1)(i)(A) | x 50 73(a)(2)(iv)(A) | 73.71(a)(4) |
| 20 2203(a)(2)(i) | 50.36(c)(1)(ii)(A) | 50 73(a)(2)(v)(A) | 73.71(a)(5) |
| 20 2203(a)(2)(ii) | 50.36(c)(2) | 50 73(a)(2)(v)(B) | OTHER |
| 20 2203(a)(2)(iii) | 50.46(a)(3)(ii) | 50 73(a)(2)(v)(C) | Specify in Abstract below or in |
| 20 2203(a)(2)(iv) | 50 73(a)(2)(i)(A) | 50 73(a)(2)(v)(D) | NRC Form 366A |
| 20 2203(a)(2)(v) | 50 73(a)(2)(i)(B) | 50 73(a)(2)(vii) | |
| 20 2203(a)(2)(vi) | 50 73(a)(2)(i)(C) | 50 73(a)(2)(viii)(A) | |
| 20.2203(a)(3)(i) | 50 73(a)(2)(ii)(A) | 50.73(a)(2)(viii)(B) | |

12. LICENSEE CONTACT FOR THIS LER

NAME

Barb Dotson, Regulatory Analyst

TELEPHONE NUMBER (Include Area Code)

(269) 764-2265

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

| CAUSE | SYSTEM | COMPONENT | MANU- FACTURER | REPORTABLE TO EPIX | CAUSE | SYSTEM | COMPONENT | MANU- FACTURER | REPORTABLE TO EPIX |
|-------|--------|-----------|-------------------|-----------------------|-------|--------|-----------|-------------------|-----------------------|
| D | FK | H | J120 | Y | | | | | |

14. SUPPLEMENTAL REPORT EXPECTED

YES (If yes, complete EXPECTED SUBMISSION DATE) X NO

15. EXPECTED
SUBMISSION
DATE

MONTH DAY YEAR

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On December 1, 2002, at approximately 2154 hours, with the plant operating at 100% power, an automatic reactor trip occurred on main generator loss of load. The loss of load occurred when a transmission tower's static line hanger failed, allowing one of two static lines to contact a 345 KV transmission line, tripping the main generator. The static line also contacted the rear bus in the switchyard that supplies the plant non-1E 4160 volt startup transformers. The rear bus tripped on a fault-to-ground causing a loss of non-1E 4160 volt AC buses. Consequently, both main feedwater pumps tripped, and the auxiliary feedwater system started automatically on low steam generator level, as expected.

The plant was maintained at or near normal operating pressure and temperature subsequent to the trip, on natural circulation, since startup power for primary coolant pumps was also lost. The plant was returned to service on December 5, 2002.

This event is reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an event that resulted in an automatic reactor trip and automatic actuation of the auxiliary feedwater system.

LICENSEE EVENT REPORT (LER)

| 1. FACILITY NAME | 2. DOCKET | 6. LER NUMBER | | | 3. PAGE |
|-------------------------|-----------|---------------|----------------------|--------------------|---------|
| PALISADES NUCLEAR PLANT | 05000255 | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | 2 OF 3 |
| | | 2002 | - 002 - | 00 | |

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

EVENT DESCRIPTION

On December 1, 2002, at approximately 2154 hours, with the plant operating at 100% power, an automatic reactor [RCT] trip occurred on main generator [GEN] loss of load. The loss of load occurred when a transmission tower's [TWR] static line hanger [H] failed, allowing one of two static lines to contact a 345 KV transmission line, tripping the main generator. The static line also contacted the rear bus [BU] in the switchyard [FK] that supplies the plant non-1E 4160 volt startup transformers [XFMR]. The rear bus tripped on a fault-to-ground causing a loss of non-1E 4160 volt AC buses. Consequently, both main feedwater pumps [P;SJ] tripped, and the auxiliary feedwater system [BA] started automatically on low steam generator [SG] level, as expected.

The plant was maintained at or near normal operating pressure and temperature subsequent to the trip, on natural circulation, since startup power for primary coolant pumps [P;AB] was also lost.

The plant was returned to service on December 5, 2002.

This event is reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an event that resulted in an automatic reactor trip and automatic actuation of the auxiliary feedwater system.

CAUSE OF THE EVENT

Inadequate preventive maintenance over a 30-year service life allowed mechanical wear of the hanger to the point of ductile failure. The additional mechanical load/force of the falling line caused a similar failure of the hanger and the pin/shoe connection on an adjacent tower. Evaluation of the event concluded that previous reviews of industry operating experience did not identify all hardware requiring inspections, which resulted in a lack of preventive maintenance activities.

SAFETY SIGNIFICANCE

The safety significance of this event was minimal. All safety systems functioned as expected during the plant trip.

LICENSEE EVENT REPORT (LER)

| 1. FACILITY NAME | 2. DOCKET | 6. LER NUMBER | | | 3. PAGE | | |
|-------------------------|-----------|---------------|----------------------|--------------------|---------|----|---|
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| PALISADES NUCLEAR PLANT | 05000255 | 2002 | - 002 - | 00 | 3 | OF | 3 |

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

CORRECTIVE ACTIONS

Authorization was obtained to operate without one static line on the section of 345 KV transmission line between the main power transformer and the switchyard. A new static line will be installed during the 2003 refueling outage, in accordance with original design.

The remaining static line was inspected and worn parts were replaced to prevent a similar event from occurring on this line. Also, the connections and conductors of the 345 KV lines were inspected with no anomalies identified.

Applicable industry operating experience is being re-evaluated and preventive maintenance activities for 345 KV components will be revised, as needed.

PREVIOUS SIMILAR EVENTS

A Consumers Energy hydro plant, Ludington Pumped Storage, had a failure of a static line hanger on October 14, 1995. The static line fell onto an arm of the tower that prevented it from contacting a conductor and creating an equipment trip. No incident report was distributed and Palisades' personnel were not previously aware of this occurrence.

PREVIOUS LERs

None